



CODE ENFORCEMENT BOARD HEARING AGENDA

FEBRUARY 28, 2017 9:00 AM

CITY COMMISSION MEETING ROOM - CITY HALL 100 N ANDREWS AVENUE FT. LAUDERDALE, FL 33301

CODE ENFORCEMENT BOARD

Code of Ordinances: Sec. 11-3.

PURPOSE: Hear and decide cases in which violations are alleged of any provision of the Florida Building Code, Broward County Amendments and violations of the Code of Ordinances of the City of Fort Lauderdale when alleged together with a violation of the Florida Building Code.

Note: If any person decides to appeal any decision made with respect to any matter considered at this public meeting or hearing he/she will need a record of the proceedings and for such purpose, he/she may need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based.

Board Members: Patrick McGee, Chair • Mark Booth, Vice Chair • Joan Hinton

- Lakhi Mohnani Peter Cooper Chris Evert Jonathan Keith Robert Smith (alternate)
- Michael Madfis (alternate) Jonathan Keith (alternate) Board Attorney: Bruce Jolly

TWO OR MORE FORT LAUDERDALE CITY COMMISSIONERS OR MEMBERS OF A CITY OF FORT LAUDERDALE ADVISORY BOARD MAY BE IN ATTENDANCE AT THIS MEETING.

HEARING SCHEDULED

CASE NO: CE16080549

CASE ADDR: 5581 NE 28 AVE

OWNER: DESIMONE, MICHAEL

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. CONSTRUCTION OF WOOD DECK IN BACK YARD.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE16081390 CASE ADDR: 1225 NW 3 ST

OWNER: MAX LLC

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

REPLACEMENT OF ELECTRICAL PANEL.
 REPLACEMENT OF ELECTRICAL OUTLETS.
 ADDITION OF ELECTRICAL FIXTURES.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE16090072 CASE ADDR: 713 NW 4 AVE

OWNER: STS GROUP USA INC INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. KITCHEN AND BATHROOM RENOVATION.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE16091583 CASE ADDR: 2140 SW 36 AV

OWNER: AGOSTINHO, MONICA

PIRES, MARCOS ANDRE

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. NEW DRIVEWAY CONSTRUCTION.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE16110266 CASE ADDR: 457 SW 28 AV

OWNER: HYPPOLITE, SANDRA INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. SHED BUILT IN BACK YARD.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16101628

CASE ADDR: 805 SW 16 ST

OWNER: EIGHT O FIVE LLC

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

- 1. BATHROOM RENOVATION.
- 2. BATHROOM ADDITION.
- 3. FRONT PORCH AND CARPORT ENCLOSURE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16101750 CASE ADDR: 3310 NE 16 ST OWNER: LOMWARD GROUP LLC INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. METAL GATE INSTALLED ON THE SIDE OF THE HOUSE.

2. ABOVE GROUND POOL INSTALLATION.

3. POOL DECK INSTALLATION.

4. SHADE STRUCTURE INSTALLED ON DRIVEWAY.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE17010728 CASE ADDR: 1017 NE 17 ST
OWNER: VIC NIC DEVELOPMENT LLC

INSPECTOR: KELVIN ARNOLD

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. INTERIOR DEMOLITION AND ALTERATIONS OF INTERIOR WALLS, MECHANICAL, ELECTRICAL AND PLUMBING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16080860 CASE ADDR: 2070 NE 62 ST

OWNER: KATZ, MICHAEL JASON

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. EXTENSIVE RENOVATIONS AND STRUCTURAL ALTERATIONS MADE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15120894

CASE ADDR: 209 N FTL BEACH BLVD 6C

OWNER: KOVEN, ANGEL

KOVEN, GARY ETAL

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS INCLUDING KITCHEN AND

BATHROOM REMODELING INCLUDING BUT NOT LIMITED TO:

A. STRUCTURAL, ELECTRICAL, PLUMBING AND MECHANICAL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16071960
CASE ADDR: 3086 HARBOR DR

OWNER: RUSTLE INVESTMENTS LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS MADE SUCH AS BATHROOM REMODELING.

2. REMOVED AND REPLACED DRYWALL/TILE BACK BOARD,

3. PLUMBING FIXTURES AND ELECTRICAL DEVICES REMOVED AND REPLACED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16111679

CASE ADDR: 2455 NE 51 ST # E116

OWNER: COSTA, PETER A INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS MADE SUCH AS A KITCHEN REMODELING INCLUDING ELECTRICAL AND PLUMBING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC (2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16121219
CASE ADDR: 2733 NE 25 PL
OWNER: MARTELLO, REGINA

MORAIS, NUNO

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. INTERIOR DEMOLITION AND ALTERATIONS OF INTERIOR WALLS, MECHANICAL, ELECTRICAL AND PLUMBING WITHOUT

THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16111690

CASE ADDR: 2841 N OCEAN BLVD # 1510

OWNER: AGUADO, JOHN

JOHN AGUADO REV LIV TR

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE TO THE PLUMBING WHICH HAS COMPROMISED THE FIRE PENETRATIONS BETWEEN FLOORS. THIS WORK WAS PERFORMED WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE17011174
CASE ADDR: 6681 NW 17 AVE

OWNER: DRSP ENTERPRISES LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

FBC(2014) 116.1.1

THIS PROPERTY HAD A SEVERE FIRE AND THE BUILDING HAS BEEN COMPLETELY DESTROYED AS A RESULT OF THIS FIRE. THE PROPERTY OWNER MUST OBTAIN THE REQUIRED DEMOLITION PERMITS TO REMOVE ALL OF THE DEBRIS AND

MAKE THE PROPERTY SAFE.

CASE NO: CE16122209

CASE ADDR: 2841 N OCEAN BLVD # 301

OWNER: FEDERAL NATIONAL MORTGAGE ASSN

% ROBERTSON, ANSCHUTZ & SCHNEID

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO INTERIOR DEMOWITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS.

- 1. THE A/C UNIT WAS REPLACED IN 2010 AND THERE IS NO PERMIT HISTORY FOR THIS REPLACED MECHANICAL UNIT.
- 2. THERE ARE ELECTRICAL VIOLATIONS WITH ROMEX WIRING IN THE RATED WALLS.
- 3. THE WATER HEATER WAS REPLACED WITHOUT THE REQUIRED PLUMBING PERMIT.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE17010286

CASE ADDR: 2595 N FEDERAL HWY

OWNER: 3157 INC INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 116.1.1

THIS PROPERTY WAS STRUCTURALLY DAMAGED AS THE RESULT OF A VEHICLE CRASHING INTO THE BUILDING AND COMPROMISING THE STRUCTURAL INTEGRITY OF THE BUILDING.

CASE NO: CE17010667
CASE ADDR: 2259 NE 20 ST
OWNER: SOFI CORP
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. REMODELING/ALTERATIONS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 116.1.1

THIS PROPERTY IS IN A DISTRESSED STATE. THE EXTERIOR WALLS ARE OPEN AND THE EXTERIOR ENVELOPE OF THE BUILDING IS COMPROMISED. THERE ARE AREAS OF THE ROOF THAT ARE SAGGING INWARD. THIS PROPERTY IS POTENTIALLY UNSAFE IN A HIGH WIND CONDITION AND POSES A THREAT TO THE NEIGHBORING PROPERTIES AND THE COMMUNITY.

CASE NO: CE16111730 CASE ADDR: 1779 SE 25 AV OWNER: MIADO LLC INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. THE INTERIOR DEMOLITION OF THE KITCHEN, BATHROOMS, INTERIOR WALLS AND A COMPLETE INTERIOR RENOVATION IN PROGRESS INCLUDING STRUCTURAL, ELECTRICAL AND PLUMBING WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16110245

CASE ADDR: 2841 N OCEAN BLVD # 2007

OWNER: BEAULIEU, LISE

GOSSELIN, MARCEL

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS KITCHEN AND BATHROOM REMODELING WITH FRAMING, DRYWALL, PLUMBING AND ELECTRICAL WORK PERFORMED WITHOUT THE REQUIRED

PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16100035

CASE ADDR: 2841 N OCEAN BLVD # 1508

OWNER: LOSE, JOHN J INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. THE KITCHEN AND BATHROOMS BEING REMODELED.
- 2. FRAMING AND DRYWALL THE CEILINGS IN THE KITCHEN AND BATHROOM.
- 3. CONVERTING A BATHTUB TO A SHOWER COMPROMISING THE FIREWALL AND THE PLUMBING PIPE SLAB PENETRATIONS.

ALL WORK HAS BEEN PERFORMED WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16111476

CASE ADDR: 2309 BARCELONA DR
OWNER: CORRELL, TODD & KARIN

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS KITCHEN AND BATHROOM REMODELING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16041244
CASE ADDR: 415 NW 7 ST

OWNER: TRUST NO 413-415

LAND TRUST SERVICE CORP TRSTEE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE

PERMIT AND INSPECTIONS:

1. INSTALLED FENCE ON PERIMETER OF PROPERTY.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16101554
CASE ADDR: 724 NW 17 ST

OWNER: SHUTTS, JASON ALBERT

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND

WINDOW PERMIT AND INSPECTIONS:

1. REMOVED WINDOW AND INSTALLED DOOR AT RIGHT

ELEVATION.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16081266 CASE ADDR: 1544 NW 15 TER

OWNER: WRIGHT, ELIZABETH C &

WRIGHT, JONATHAN

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NO PERMIT FOR BACKYARD STRUCTURE. NOW OCCUPIED AS LIVING SPACE.

2. REMODELED KITCHEN AND BATHROOM INCLUDING TILE BACKER IN WET AREAS.

- 3. ADDED 2 KITCHENS. ONE IN THE CONVERTED CARPORT AND THE OTHER IN THE BACKYARD STRUCTURE.
- 4. ALTERED THE INTERIOR FLOOR PLAN OF MAIN RESIDENCE.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLED PLUMBING FIXTURES IN BATHROOM AND KITCHEN.
- 2. PLUMBING FOR 2 ADDED BATHROOMS AND KITCHENS.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLED NEW CIRCUITS FOR A/C SYSTEM.
- 2. INSTALLED NEW LIGHTING FIXTURES AND CIRCUITS.
- 3. INSTALLED NEW OUTLETS IN KITCHEN.
- 4. INSTALLED ELECTRICAL PANEL.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6)
GFI'S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52

R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS: WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLED A SPLIT MECHANICAL A/C SYSTEM.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. INSTALLED DOORS AND WINDOWS.

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF SINGLE FAMILY TO THAT OF 3-FAMILY SERVED BY A SINGLE ELECTRICAL METER WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE11040091
CASE ADDR: 509 NW 20 AV
OWNER: RETLEY, LELA EST

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2007) 105.1

THE BUILDING HAS BEEN CHANGED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS OR INSPECTIONS:

- 1. MOST OF THE WINDOWS AT THE DWELLING WERE REPLACED.
- AN EXTERIOR DOOR WAS REPLACED AT THE REAR OF THE PROPERTY

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. THE FAUCET FOR THE TUB, THE LAVATORY AND VANITY, AND THE TOILET WERE REPLACED IN THE BATHROOM.

FBC(2007) 1612.1.2

ALL THE WINDOWS, AND DOOR INSTALLATIONS HAVE NOT BEEN DEMONSTRATED TO WITHSTAND THE REQUIRED WIND LOADING THROUGH THE PERMITTING PROCESS.

FBC(2007) 1626.1

THE WINDOWS AND DOORS THAT HAVE BEEN INSTALLED DO NOT PROVIDE THE REQUIRED RESISTANCE TO THE IMPACT OF WINDBOURNE DEBRIS. AN APPROVED SHUTTER SYSTEM HAS NOT BEEN PROVIDED.

._____

CASE NO: CE16121631 CASE ADDR: 1920 S OCEAN DR

OWNER: ATLANTIC TOWERS CORP

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. OPENED SHAFT ENCLOUSRE FOR RISERS THAT
PENETRATES ALL FLOORS IN THIS MULTI-STORY
HIGH-RISE BUILDING.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. REPLACED HEAT EXCHANGE RISER PIPES FOR COOLING TOWER WITHIN SHAFT ENCLOSURE ON MULTIPLE FLOORS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS

CASE NO: CE16090428
CASE ADDR: 1408 NW 3 AVE

OWNER: CR INVESTMENTS SOLUTION LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR REMODELING, INCLUDING REPLACEMENT OF TILE-BACKER IN WET AREAS.
- 2. INTERIOR REMODELING INCLUDING KITCHEN AND BATHROOMS.
- 3. CMU BLOCK OVER EXISTING OPENINGS ON EXTERIOR WALLS.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLATION OF SPLIT MECHANICAL A/C SYSTEMS.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. INSTALLATION OF WINDOWS AND DOORS.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. INSTALLATION OF NEW FENCING.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF PLUMBING FIXTURES IN BATHROOM AND KITCHEN.
- 2. INSTALLATION OF TANKLESS WATER-HEATER.
- 3. INSTALLATION OF WATER SUPPLY LINES AND WASTE LINES.

INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:
INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO:

1. INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING, ELECTRONIC MONITORING SYSTEMS, FIRE ALARMS, BURGLAR ALARMS AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY

WITH 406.4 (D)(1) THRU (D)(6) GFI'S REQUIRED AS PER NEC 108.8 OUTLET SPACING AS REQUIRED UNDER NEC 210.52

R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS: WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 115.1

A STOP WORK ISSUED.

STOP WORK ORDER ISSUED SINCE WORK IS ONGOING WITHOUT THE REQUIRED PERMITS. VIOLATION OF STOP WORK ORDER IS SUBJECT TO THE MAXIMUM PENALTIES AS OUTLINED UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

CASE NO: CE16050886 CASE ADDR: 1433 NW 3 AV

OWNER: HIZUENGA 1433 LAND TR

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. STRUCTURAL WORK IN PROGRESS ON EXTERIOR OF BUILDING.
- 2. INTERIORS WALLS HAVE BEEN REMOVED.
- 3. STRUCTURAL OPENINGS AROUND WINDOWS HAVE BEEN MODIFIED.
- 4. WALLS IN BATHROOM HAVE BEEN OPENED AND COVERED WITH DURA-ROC.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. WINDOWS AND DOORS HAVE BEEN INSTALLED.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. GATES AND FENCE HAVE BEEN INSTALLED.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. CHANGING AND INSTALLING NEW PLUMBING FIXTURES IN KITCHEN AND BATHROOMS.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. REPLACING ELECTRICAL FIXTURES, SWITCHES AND OUTLETS.
- 2. REWIRING FOR ELECTRICAL FIXTURE REPLACEMENT.
- 3. REWIRING AND RECONFIGURING BREAKER PANEL.
- 4. REWIRING FOR ELECTRICAL FIXTURE REPLACEMENT.

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS/PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS

FBC(2014) 115.1

A STOP WORK WAS ISSUED.

STOP WORK ORDER ISSUED SINCE WORK IS ONGOING WITHOUT THE REQUIRED PERMITS. VIOLATION OF STOP WORK ORDER IS SUBJECT TO THE MAXIMUM PENALTIES AS OUTLINED UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

CASE NO: CE16051413 CASE ADDR: 2009 SE 24 AV

OWNER: HUDSON, DARYL PAUL

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REPLACING ONSITE DRIVEWAY.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. INSTALLATION OF IMPACT WINDOWS AND DOORS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16061695 CASE ADDR: 1206 NW 11 PL

OWNER: DRAGOSLAVIC, SLAVOLJUB & MARA

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR REMODEL INCLUDING BATHROOM WET AREA.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF NEW FIXTURES IN BATHROOMS AND KITCHEN.
- 2. WATER HEATER.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. INSTALLATION OF FIXTURES INCLUDING ELECTRICAL PANEL.

R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS: WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL

BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS

CASE NO: CE16101768
CASE ADDR: 1700 NW 26 AVE

OWNER: FREEDOM MORTGAGE CORP

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. KITCHEN AND BATHROOM REMODEL.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. PLUMBING FIXTURES IN KITCHEN AND BATHROOM.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. REPLACEMENT OF METER BASE.
- 2. REPLACEMENT OF MAIN DISCONNECT PANEL.
- 3. INSTALLATION OF RECEPTACLES.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH NEC 406.4 (D)(1) THRU (D)(6)
GFI'S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52

R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS:
WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT
OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED
WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

FBC(2014) 105.3.1.4.10

THE FOLLOWING DESCRIBED WORK REQUIRES A ROOF PERMIT AND INSPECTIONS:

1. THE SLOPED PORTION OF THE ROOF WAS REPLACED IN 2009.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF MECHANICAL CENTRAL A/C SYSTEM.
- 2. INSTALLTION OF DUCT WORK.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16061719 CASE ADDR: 1736 NW 18 ST

OWNER: PRIME PROSPECT PROPERTIES LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR REMODELING INCLUDING BATHROOM WET AREAS.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLATION OF NEW MECHANICAL SPLIT A/C SYSTEM.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF NEW WATER SUPPLY LINES.
- 2. INSTALATION OF NEW WASTE LINES.
- 3. INSTALLATION OF NEW FIXTURES.
- 4. INSTALLATION OF TANKLESS WATER HEATER.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF NEW BREAKER PANEL.
- 2. INSTALLATION OF NEW WIRING CIRCUITS.
- 3. INSTALLATION OF NEW FIXTURES.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6)
GFI'S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16070791 CASE ADDR: 1107 NW 7 AVE

OWNER: BUY RENT SELL NOW LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

1. NEW SEWER CONNECTION ON PARKING LOT.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

PLUMBING ALTERATIONS, MODIFICATIONS, HAVE

COMMENCED PRIOR TO OBTAINING THE REQUIRED PERMITS.

THIS INCLUDES FIXTURES, SUPPLY LINES, WASTE

DISPOSAL AND IRRIGATION.
1. NEW SEWER CONNECTION.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16080203

CASE ADDR: 2520 YACHT CLUB BLVD OWNER: DAVID NEAL COOPER TR

COOPER, DAVID NEAL TRSTEE ETAL

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. PLACED GRAVEL IN THE SWALE WITHOUT THE REQUIRED

APPROVAL FROM ENGINEERING.

FBC(2014) 105.3.1.4.8

THE FOLLOWING DESCRIBED WORK REQUIRES A PERMIT AND INSPECTIONS:

1. NEW COVERED PERGOLA INSTALLED IN BACK YARD.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. NEW FENCE AND GATES INSTALLED ON BOTH SIDES OF FRONT ELEVATION.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16080218
CASE ADDR: 1990 SW 9 ST

OWNER: ZARAZA SERVICES LLC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. NEW WOOD DECKS INSTALLED.
- 2. NEW A/C INSTALLED.
- 3. NEW KITCHEN CABINETS INSTALLED.
- 4. NEW PLUMBING FIXTURES INTALLED.
- 5. NEW ELECTRICAL INSTALLATION FOR A/C UNITS.

FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO:

1. INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCT WORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL. INSTALLED NEW A/C UNIT WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.15

ALTERATIONS, REPLACEMENT OR REPAIR OF EXTERIOR OPENINGS TO THE BUILDING ENVELOPE WILL REQUIRE PERMITS. THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REPLACEMENT OF EXTERIOR DOORS AND WINDOWS.
WINDOWS AND DOORS HAVE BEEN REPLACED WITHOUT
SUBMITTING THE REQUIRED PRODUCT APPROVALS TO MEET
HIGH VELOCITY HURRICANE ZONE STANDARDS FOR OPENING
PROTECTION.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO:

1. INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO:

1. INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING, ELECTRONIC MONITORING SYSTEMS, FIRE ALARMS, BURGLAR ALARMS AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16090315
CASE ADDR: 2300 NW 6 ST
OWNER: RSKYR LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO: ALTERING, REPAIRING, INSTALLATION OF PLUMBING

COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT

LIMITED TO:

PLUMBING ALTERATIONS, MODIFICATIONS, HAVE COMMENCED PRIOR TO OBTAINING THE REQUIRED PERMITS. THIS INCLUDES FIXTURES, SUPPLY LINES, WASTE DISPOSAL AND IRRIGATION.

ALL PLUMBING ALTERATIONS MODIFICATIONS AND REPAIRS UNDER THE SECTION OF THIS CODE.

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. NEW SEWER PIPE INSTALLED CONNECTING THE CLEAN OUT

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16090674
CASE ADDR: 1421 NW 7 AV
OWNER: CENOVSKI, NATHAN

STEPHENSON, LARA

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. FRONT PORCH ENCLOSED WITHOUT PERMIT.

FBC (2014) 110.6

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY THE RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS

AND/OR DETERMINATION OF COMPLIANCE WITH THE

FLORIDA BUILDING CODE.

CASE NO: CE16090939 CASE ADDR: 1135 NE 11 AV

OWNER: SCHNEIDER, RUSSELL INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

- THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. NO PERMITS ON ADDITIONS AND REMODELING.
- 2. ADDITION AND ROOFING INSTALLED ON BACK OF HOUSE. NO PERMITS.
- 3. FLAT ROOF HAS FRAMING WITH MESH SET UP ON OUTSIDE OF HOUSE ROOF.
- 4. NEW WINDOWS AND DOORS INSTALLED ON ENTIRE HOUSE. LEFT SIDE HOUSE DOORS AND WINDOWS REMOVED AND CONCRETE BLOCK INSTALLED. NO PERMITS.
- 5. FENCING TRELLIS ON INSIDE OF PROPERTY. LEFT AND RIGHT SIDE OF HOUSE HIGER THEN CODE. VISIBLE FROM ROAD.
- 6. ENTIRE HOUSE REMODELED KITCHEN & 2 BATHROOMS AND WALLS MOVED WITH PLUMBING UPGRADES.
- 7. FLORIDA ROOM ENCLOSED TO BEDROOM. NO PERMITS.
- 8. FULL ELECTRICAL UPGRADE ON INSIDE. NO PERMITS.

CASE NO: CE16091837 CASE ADDR: 2675 SW 13 ST

OWNER: LONE PALM PROPERTIES LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

- 1. BACK PORCH ENCLOSURE.
- 2. NEW DOORS AND WINDOWS.
- 3. NEW ELECTRICAL WIRING.

FBC(2014) 105.3.1.4.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BACK PORCH ENCLOSED.

FBC(2014) 105.3.1.4.15

ALTERATIONS, REPLACEMENT OR REPAIR OF EXTERIOR OPENINGS TO THE BUILDING ENVELOPE WILL REQUIRE PERMITS. THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW EXTERIOR DOORS AND WINDOWS INSTALLED ON BACK PORCH ENCLOSURE.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW ELECTRICAL WIRING FOR BACK PORCH ENCLOSURE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16101151 CASE ADDR: 2115 SE 18 ST

OWNER: BOAT HOUSE POOL INC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

1. NEW DOCK INSTALLED.

FBC(2014) 105.3.1.4.1

THE ERECTION OR CONSTRUCTION OF ANY BUILDING OR STRUCTURE, THE ADDING TO, ENLARGING, REPAIRING, IMPROVING, ALTERING, COVERING OR EXTENDING OF ANY

BUILDING OR STRUCTURE.
1. NEW DOCK INSTALLED

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16110276

CASE ADDR: 1310 BRICKELL DR

OWNER: ALLEN, ISABEL C & JAMES F

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW PAVER DRIVEWAY INSTALLED.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16110792

CASE ADDR: 1334 AVOCADO ISLE
OWNER: MCCABE, JAMES J III
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW PAVER DRIVEWAY.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

IND IDMITTING INCODES

CASE NO: CE16111320 CASE ADDR: 323 MOLA AV

OWNER: ASHITA HOMESTEAD LLC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. NEW FRENCH DOORS INSTALLED ON WEST AND NORTH ELEVATIONS.
- NEW METAL FRAME ROOF INSTALLED ON NORTH ELEVATION.

FBC(2014) 105.3.1.4.10

THE FOLLOWING DESCRIBED WORK REQUIRES A ROOF PERMIT AND INSPECTIONS:

1. NEW METAL FRAME ROOF INSTALLED NORTH ELEVATION.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. NEW FRENCH DOORS INSTALLED NORTH AND WEST ELEVATIONS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

.-----

CASE NO: CE16111516

CASE ADDR: 2437 GULFSTREAM LN
OWNER: NAGEN, MARY ELENA
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

- 1. PLUMBING PIPES INSTALLED FOR POOL ON SOUTH SIDE OF PROPERTY.
- 2. NEW BRICK PATIO AROUND THE POOL.

FBC(2014) 105.3.1.4.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. NEW BRICK PATIO INSTALLED AROUND THE POOL.
- 2. DEMOLISHED AND CONSTRUCTED A NEW ASPHALT DRIVEWAY.
- 3. DEMOLISHED EXTERIOR PERGOLA STRUCTURE.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. NEW PLUMBING PIPES AND CONNECTIONS FOR THE POOL ON SOUTH SIDE OF THE PROPERTY.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16111726 CASE ADDR: 3633 SW 17 ST

OWNER: PENA, DAVID & ALMA LORENA

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

1. NEW ROOF COVERING.

FBC(2014) 105.3.1.4.10

THE FOLLOWING DESCRIBED WORK REQUIRES A ROOF

PERMIT AND INSPECTIONS:
1. NEW ROOF COVERING.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

._____

CASE NO: CE16120177
CASE ADDR: 210 NURMI DR
OWNER: NURMI HOUSE LLC
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

1. SMOKE/CARBON MONOXIDE DETECTOR INSTALLED.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN

ELECTRICAL PERMIT AND INSPECTIONS:

1. SMOKE/CARBON MONOXIDE DETECTORS SYSTEM

INSTALLED.

CASE NO: CE16120322
CASE ADDR: 1336 SW 19 AV
OWNER: MELLINGER, PAUL C
MELLINGER, MEGAN

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

1. WOOD FENCE INSTALLED, NO PERMIT HISTORY.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE

PERMIT AND INSPECTIONS:

1. FENCE INSTALLED ON PROPERTY PERIMETER.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16120882

CASE ADDR: 616 INTRACOASTAL DR

OWNER: 616 INTRACOASTAL DRIVE LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

1. NEW WOOD FENCE INSTALLED UNDER PERMIT 1609052

FOR A TEMPORARY CONSTRUCTION FENCE.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE

PERMIT AND INSPECTIONS:

1. NEW WOOD FENCE INSTALLED UNDER THE WRONG PERMIT

BLOCKING WATER METERS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS

APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16121351 CASE ADDR: 3305 SW 22 ST

OWNER: WITHROW-BENNETT, LISA

BENNETT, JONATHAN

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING

PERMIT AND INSPECTIONS:

1. NEW SPRINKLER SYSTEM INSTALLED.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS

APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16121452 CASE ADDR: 1614 NW 2 AV

OWNER: KNIGHT, PATRICIA A INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. NEW DOORS AND WINDOWS INSTALLED.
- 2. KITCHEN RENOVATION.
- 3. BATHROOM RENOVATION, SANITARY FIXTURES REPLACED.
- 4. INTERIOR DEMOLITION.

FBC(2014) 105.3.1.4.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR DEMOLITION.
- 2. KITCHEN REMODELING.
- 3. BATHROOMS REMODELING.
- 4. NEW IMPACT DOORS AND WINDOWS INSTALLED.
- 5. NEW ELECTRICAL WIRING.

FBC(2014) 105.3.1.4.15

NEW WINDOWS AND DOORS HAVE BEEN REPLACED WITHOUT SUBMITTING THE REQUIRED PRODUCT APPROVALS TO MEET HIGH VELOCITY HURRICANE ZONE STANDARDS FOR OPENING PROTECTION.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT LIMITED TO:

1. NEW PLUMBING FIXTURES IN KITCHEN AND BATHROOMS.

FBC(2014) 105.3.1.4.5

COMMENCING ELECTRICAL ALTERATIONS AND MODIFICATIONS PRIOR TO OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO THE INSTALLATION OF NEW ELECTRICAL PANEL, LIGHT FIXTURES, WALL OUTLETS, SWITCHES, AC SUPPLY AND METER BASE.

1. NEW ELECTRICAL WIRING/OUTLETS FOR KITCHEN.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

._____

CASE NO: CE16121633
CASE ADDR: 2201 NE 16 ST
OWNER: EDWARDS, RANDY L
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW PAVER DRIVEWAY AND CONCRETE GARDEN WALLS.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16121682
CASE ADDR: 1521 SW 4 AVE
OWNER: WILLIAMS, JOSIE
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

1. NEW PAVER DRIVEWAY INSTALLED.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16122045
CASE ADDR: 540 NW 7 AVE
OWNER: MJDC AOA LLC

% MILTON JONES DEV CORP

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

1. RESURFACING AND RESTRIPPING OF PARKING LOT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

.-----

RETURN HEARING (OLD BUSINESS)

CASE NO: CE14061177 CASE ADDR: 3505 SW 12 CT

OWNER: MCFARLANE, CHRISTINE INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND THE CERTIFICATE OF OCCUPANCY:

- 1. THE GARAGE OR CARPORT WAS ENCLOSED INTO LIVING SPACE WITHOUT A C.O.
- 2. THE WINDOWS IN THE DWELLINGS' OPENINGS WERE REPLACED.
- 3. THE KITCHEN AND BATHROOM WERE UPGRADED WITH NEW PLUMBING AND ELECTRICAL FIXTURES.
- 4. NEW CABINETRY WAS INSTALLED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15062080

CASE ADDR: 4881 NW 9 TER

OWNER: CHARLES, ANNEMISE

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

WINDOW OPENING WAS ENCLOSED.
 CENTRAL A/C UNIT WAS REPLACED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

CASE NO: CE16051188
CASE ADDR: 1201 NW 16 CT

OWNER: CHEVEULON, NERUBIN H/E

CHEVEULON, LEDILE LP

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. WOOD FENCE REPLACEMENT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

CASE NO: CE16062033
CASE ADDR: 3130 NW 69 CT
OWNER: REYNA, KATHERINE M
INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. CENTRAL AIR CONDITIONER REPLACEMENT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16072027
CASE ADDR: 1606 NW 14 AV
OWNER: VIRGO, DANNY LEE
INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. WOOD FENCE INSTALLATION.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15010862

CASE ADDR: 2679 MARATHON LN
OWNER: DA ROSA, JOSE SIMOES

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CARPORT AND PORTIONS OF THE BUILDING HAVE BEEN CLOSED IN, INCLUDING WINDOWS AND DOORS.

FBC(2010) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BATHROOM INSIDE THE ENCLOSED SECTION OF THE CARPORT.

FBC(2010) 105.4.5

THE ELECTRICAL IN THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRICAL SUPPLY CLOSED IN PORTIONS OF THE BUILDING.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15042161
CASE ADDR: 2505 NW 20 ST
OWNER: IRVIN, DOROTHY H

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CONSTRUCTION HAS CONTINUED WITH EXPIRED

PERMITS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15051829
CASE ADDR: 1804 NW 16 CT
OWNER: TUCHOW, TYLER
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. THE CARPORT HAS BEEN ENCLOSED.

2. PLUMBING, ELECTRICAL & MECHANICAL WORK HAVE BEEN DONE WITHIN THE ENCLOSED CARPORT FOR A BATHROOM AND WASHER AND DRYER.

FBC(2010) 105.4.5

THE ELECTRICAL IN THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRICAL SUPPLYING THE ENCLOSED CARPORT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2010) 111.1.1

USE AND OCCUPANCY. NO BUILDING OR STRUCTURE SHALL BE USED OR OCCUPIED, AND NO CHANGE IN THE EXISTING OCCUPANCY CLASSIFICATION OF A BUILDING OR STRUCTURE OR NATURE OR USE OR PORTION THEREOF SHALL BE MADE UNTIL THE BUILDING OFFICIAL HAS ISSUED A CERTIFICATE OF OCCUPANCY THERE FOR AS PROVIDED HEREIN. SAID CERTIFICATE SHALL NOT BE ISSUED UNTIL ALL REQUIRED ELECTRICAL, GAS, MECHANICAL, PLUMBING AND FIRE PROTECTION SYSTEMS, AND PROVISIONS OF FFPC HAVE BEEN INSPECTED FOR COMPLIANCE WITH THE TECHNICAL CODES AND OTHER APPLICABLE LAWS AND ORDINANCES AND RELEASED BY THE BUILDING OFFICIAL. ISSUANCE OF A CERTIFICATE OF OCCUPANCY SHALL NOT BE CONSTRUED AS AN APPROVAL OF A VIOLATION OF THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION.

CASE NO: CE15081055
CASE ADDR: 1208 NW 19 AV
OWNER: GREEN, LINDA
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED To:

- 1. INTERIOR REMODELING AND ALTERATIONS WITHOUT OBTAINING THE REQUIRED PERMITS.
- 2. BUILDING A SHED IN THE BACK YARD WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.11

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLING AN AIR CONDITIONING CONDENSER UNIT WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.4

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLING AN IRRIGATION SYSTEM WITH WELL PUMP AND TIMER WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 105.3.1.4.5

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLING ELECTRICAL FOR IRRIGATION SYSTEM WITH WELL PUMP AND TIMER WITHOUT OBTAINING THE REQUIRED PERMITS.

CASE NO: CE15082171
CASE ADDR: 2841 SW 9 ST

OWNER: VERNEUS, ALPHONSINE H/E

GASTON, IBRAM

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. DEN CONVERTED TO AN EFFICIENCY APARTMENT WITH A BATHROOM.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILT A BATHROOM IN THE DEN WITHOUT ACQUIRING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ALTERED THE ELECTRICAL SYSTEM IN THE COVERTED DEN TO EFFICIENCY WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. INSTALLED A CENTRAL A/C CONDENSOR UNIT WITHOUT THE REQUIRED PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A DUPLEX TO A FOURPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

1. CONVERTED DEN TO AN EFFICIENCY.

FBC(2014) 116.2.1.2.5

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE. IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED: FIRE DAMAGE IN THE BUILDING IS A POTENTIAL LIFE AND SAFETY HAZARD SINCE THE BUILDING IS STILL ENERGIZED AND OCCUPIED.

CASE NO: CE15092413 CASE ADDR: 1536 NW 5 AV

OWNER: MERCADO, REINALDO J PEREZ H/E

KARAMANOGLOU, ALEX

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. EXTENSIVE REMODELING AND ALTERATIONS WITHOUT OBTAINING THE REQUIRED PERMITS MAY BE CITED IF DISCOVERED DURING THE CONSTRUCTION PROCESS. THIS INCLUDES STRUCTURAL ALTERATIONS MADE TO THE ROOF AND WALL STRUCTURE OF THE BUILDING.

FBC(2014) 105.3.1.4.10

THE FOLLOWING WORK REQUIRES A ROOF PERMIT AND INSPECTIONS:

1. RE-ROOFED THE STRUCTURE PRIOR TO OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.11

THE FOLLOWING WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. THE REPLACEMENT OF THE EVAPORATOR UNIT, THERMOSTAT, THE CONDENSER UNIT, ALL REGISTERS AND ELECTRICAL CIRCUITS.

FBC(2014) 105.3.1.4.3

THE FOLLOWING WORK REQUIRES A DEMOLITION PERMIT AND INSPECTIONS:

1. COMPLETE INTERIOR DEMOLITION HAS BEEN PERFORMED PRIOR TO OBTAINING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.4

THE FOLLOWING WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. PLUMBING ALTERATIONS, MODIFICATIONS, HAVE COMMENCED PRIOR TO OBTAINING THE REQUIRED PERMITS. THIS INCLUDES FIXTURES, SUPPLY LINES, WASTE DISPOSAL, IRRIGATION AND R & R SINKS/WATER BASINS.

FBC (2014) 105.3.1.4.5

THE FOLLOWING WORK REQUIRES AN ELECRICAL PERMIT AND INSPECTIONS:

1. THE INSTALLATION OF NEW ELECTRICAL PANEL, LIGHT FIXTURES, RE-WIRING, WALL OUTLETS, SWITCHES, A/C SUPPLY AND METER BASE.

FBC(2014) 107.1.1

SUBMITTAL OF 2 SETS OF PLANS AND SPECIFICATIONS AS OUTLINED IN THIS SECTION OF THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 115.1

DUE TO THE ONGOING NATURE OF THE WORK WITHOUT PERMITS A STOP WORK ORDER HAS BEEN ISSUED AND ANY FURTHER WORK AND ALTERATIONS MAY BE SUBJECT TO THE MAXIMUM PENALTIES OF \$500 PER DAY FOR VIOLATIONS OF THIS SECTION OF THE FLORIDA BUILDING CODE.

FBC(2014) 116.2.1.3.1

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE. IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED.

WORK WITHOUT PERMITS DEEMED THIS BUILDING AS UNSAFE AND SUBJECT TO BOARD-UP AND/OR DEMOLITION UNDER THE SECTION OF THIS CODE.

CASE NO: CE15101425

CASE ADDR: 640 TENNIS CLUB DR # 308

OWNER: RUBINSTEIN, GARY

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REMODELING AND ALTERATIONS WITHOUT OBTAINING THE REQUIRED PERMITS. REMOVAL OF KITCHEN CABINETS AND ALTERATION OF SOFFITS AND CEILING.

FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCTWORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL SYSTEM.

1. DUCT WORK HAS BEEN MODIFIED.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

1. SINK HAS BEEN REMOVED AND THE PLUMBING SYSTEM HAS BEEN MODIFIED.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

1. OUTLETS AND FIXTURES HAVE BEEN REMOVED AND THE ELECTRICAL SYSTEM MODIFIED.

FBC(2014) 105.3.1.5

WHERE APPLICABLE PERMIT REQUIREMENTS MUST HAVE SUPPORTING DOCUMENTATION FROM A QUALIFIED DESIGN PROFESSIONAL.

SUBMIT 2 SETS OF DRAWINGS/PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

MODIFICATIONS MADE PRIOR TO OBTAINING THE REQUIRED PERMITS MAY BE REQUIRED TO BE UNCOVERED FOR INSPECTIONS AND/OR CERTIFIED BY A LICENSED DESIGN PROFESSIONAL SOLELY AT THE DISCRETION OF THE BUILDING OFFICIAL. THIS INCLUDES BUT IT IS NOT LIMITED TO, ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 115.1

A STOP WORK WAS ISSUED.

STOP WORK ORDER ISSUED SINCE WORK IS ONGOING WITHOUT THE REQUIRED PERMITS. VIOLATION OF STOP WORK ORDER IS SUBJECT TO THE MAXIMUM PENALTIES AS OUTLINED UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

DUE TO THE ONGOING NATURE OF THE WORK WITHOUT PERMITS A STOP WORK ORDER HAS BEEN ISSUED AND ANY FURTHER WORK AND ALTERATIONS MAY BE SUBJECT TO THE MAXIMUM PENALTIES OF UP TO \$500 PER DAY PER VIOLATION UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

CASE NO: CE15120733

CASE ADDR: 1017 E LAS OLAS BLVD
OWNER: PRESTONS HOLDING LAND TR
ULMER, JAMES I TRSTEE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. MEZZANINE/ATTIC PLATFORM BUILT OVER MENS ROOM.

NOT PERMITTED PLANS. AREA BEING USED AS STORAGE AND

MAKESHIFT OFFICE. NO ENGINEERING TO DETERMINE IF

RATE FOR LOAD.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16010842
CASE ADDR: 2312 NW 14 ST
OWNER: PERSAUD, OMCHAND

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. BUILT A SECOND BATHROOM.

2. BUILT CHASES TO CONCEAL DUCT WORK.

PERMITS REQUIRED:

1. BUILDING

2. ELECTRICAL

3. MECHANICAL

4. PLUMBING

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- BATHROOM ADDITION:
 1. ADDED TOILET.
- 2. ADDED VANITY SINK.
- 3. ADDED SHOWER WITH PAN.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM. THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRICAL SYSTEM HAS BEEN ALTERED AND THE WIRING MODIFIED. FLIPPING ALL THE BREAKERS TO THE OFF POSITION DOES NOT DISCONNECT THE POWER TO ALL FIXTURES AND OUTLETS.

FBC(2014) 109.3.3

THIS CODE CASE WILL REQUIRE ALL PERMITS ISSUED AFTER WORK HAS COMMENCED, AFTER THE FACT, TO BE DOUBLE FEE.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT, THROUGHOUT THE PERMITTING PROCESS.

9-259

WATER DAMAGE FROM LEAKING ROOF HAS MADE THE RESIDENCE UNINHABITABLE. CEILING HAS FALLEN EXPOSING RAFTERS.

FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCTWORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL SYSTEM.

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: CENTRAL A/C SYSTEM

- 1. NEW CONDENSOR UNIT. MANUFACTURE DATE 08/2015.
- 2. NEW EVAPORATOR UNIT. MANUFACTURE DATE 08/2015.
- 3. ADDED EXHAUST VENT IN BATHROOM ADDTION.

FBC(2014) 116.2.1.2.5

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRICAL SYSTEM HAS BEEN ALTERED AND THE WIRING MODIFIED. FLIPPING ALL THE BREAKERS TO THE OFF POSITION DOES NOT DISCONNECT THE POWER TO ALL FIXTURES AND OUTLETS.

A LETTER FROM A CERTIFIED AND LICENSED ELECTRICIAN IS REQUIRED TO DEEM THE STRUCTURE SAFE FOR OCCUPANCY.

NEC(2005) 110.27

BREAKER PANEL HAS MISSING BLANKS AND LIVE PARTS ARE EXPOSED.

NEC (2005) 440.22 (C)

THE POWER SUPPLY AND THE A/C UNIT ARE NOT COMPATIBLE TO MANUFACTURERS SPECIFICATION AND CAUSES THE CIRCUITS TO OVERHEAT AND GIVE OFF A BURNING ODOR.

CASE NO: CE16011101 CASE ADDR: 1701 NE 9 ST

OWNER: CLARK, CLIFFORD T

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. CONVERTED GARAGE TO LIVING SPACE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF DUPLEX WITH A GUESTHOUSE TO A SIXPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE16021479
CASE ADDR: 527 N BIRCH RD

OWNER: BEACH HOUSE VILLAS LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: 47-20.20.I.

1. SEAL COATING AND RESTRIPING PARKING AREA.

FBC(2014) 105.1

THIS BUILDING/FACILITY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. SEAL COATING AND RESTRIPING PARKING AREA.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16041787
CASE ADDR: 508 NW 15 AV
OWNER: CHIWARA, GRACE
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ROOF STRUCTURE HAS BEEN ALTERED TO CREATE UTILITY CLOSET.
- 2. ALTERED INTERIOR WALL TO CONVERT TO DUPLEX.
- 3. ADDED KITCHEN FOR SECOND APARTMENT UNIT.
- 4. ADDED BATHROOM FOR SECOND APARTMENT UNIT.

FBC (2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLED PLUMBING FIXTURES IN KITCHENS AND BATHS.
- 2. INSTALLED PVC WASTE LINES IN KITCHEN.
- 3. INSTALLED PVC WASTE LINES ON EXTERIOR CONNECTED TO SANITARY SEWER SYSTEM.
- 4. INSTALLED WATER HEATER. HOT WATER SIDE IS PVC.
- 5. TPR VALVE MISSING EXTENSION.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLED WIRING FOR CENTRAL A/C SYSTEM.
- 2. INSTALLED WIRING CIRCUITS IN CARPORT.
- 3. INSTALLED WIRING CIRCUITS FOR WATER HEATER.
- 4. REPLACED BREAKER PANEL.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. INSTALLED SPLIT A/C MECHANICAL SYSTEM WHICH INCLUDES CONDENSER UNIT AND EVAPORATOR UNIT.
- INSTALLED DUCT WORK FOR CENTRAL A/C MECHANICAL SYSTEM.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. INSTALLED WINDOWS AND DOORS. NOT RELATED TO WINDOW ATF WINDOW PERMIT 15072197.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. INSTALLED FENCE IN BACK YARD.

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS/PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPE OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF SINGLE FAMILY TO A DUPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

NEC(2005) 408.38

ELECTRICAL BOXES MISSING COVER EXPOSING ENERGIZED ELECTRICAL CONNECTIONS.

NEC(2005) 110.27

ALL OUTLETS AND SWITCHES MUST HAVE COVERS AS TO NOT EXPOSE ENERGIZED ELECTRICAL CONNECTIONS.

CASE NO: CE16070941 CASE ADDR: 3648 SW 17 ST

OWNER: CONTRERAS, DELIO D

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INSTALLED ROOF STRUCTURE AT FRONT ENTRY FABRICATED FROM HURRICANE SHUTTERS.
- 2. INSTALLED ROOF STRUCTURE IN BACK YARD FABRICATED FROM HURRICANE SHUTTERS.
- 3. FABRICATED LAUNDRY ROOM STRUCTURE IN BACK YARD.
- 4. INSTALLED PREFABRICATED SHED AT BACK YARD.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLATION OF SPLIT MECHANICAL A/C SYSTEM.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF PLUMBING IN KITCHEN INCLUDING NEW SINK AND WASTE LINES.
- 2. LAUNDRY ROOM PLUMBING.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLED ELECTRICAL IN LAUNDRY ROOM.
- 2. INSTALLATION OF ELECTRICAL CIRCUITS, OUTLETS AND FIXTURES IN LAUNDRY ROOM.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6)

GFI'S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16091949
CASE ADDR: 545 NE 13 AV
OWNER: KREMEN, RONEN
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

FBC (2014) 111.1.1

SINGLE FAMILY STRUCTURE BEING OCCUPIED WITHOUT OBTAINING THE REQUIRED CERTIFICATE OF OCCUPANCY IN VIOLATION OF THIS SECTION OF THE FLORIDA BUILDING CODE.

CASE NO: CE16110799
CASE ADDR: 630 NW 14 AV
OWNER: WHEELER, ALMA T

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 1029.4

1. INSTALLED PERMANENT GRILL OVER WINDOWS BLOCKING THE EMERGENCY ESCAPE AND RESCUE OPENINGS.

FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. PERMANENTLY PLACED GRILLS OVER WINDOWS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16120747

CASE ADDR: 800 NW 11 AVE

OWNER: 800 NW 11 AVE LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 1013.4

- 1. OPENING ON GUARDRAILS EXCEED THE MAXIMUM ALLOWABLE UNDER THE SECTIONS OF THIS CODE OF 4 INCHES.
- 2. STAIR RAILING ON WEST SIDE OF BUILDING HAS FAILED.
- 3. THIS IS AN EXIGENT LIFE AND SAFETY HAZARD THAT IMMEDIATE ATTENTION IS REQUIRED TO MAKE SAFE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16050226

CASE ADDR: 728 NW 6 AVE # A OWNER: CASALE, ROSANNE D

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. FRAMED AND INSTALLED DRYWALL ON OFFICE

ENCLOSURE IN THIS WAREHOUSE.

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

 INSTALLED NEW ELECTRICAL CIRCUITRY AND FIXTURES, INCLUDING LOW VOLTAGE CIRCUITS.
 NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLED SPLIT A/C MECHANICAL SYSTEM.
NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16062301

CASE ADDR: 745 W EVANSTON CIR

OWNER: MENDOZA, MARIA TERESA H/E

GARCIA, CARLOS ALBERTO

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.10

THE FOLLOWING DESCRIBED WORK REQUIRES A ROOF

PERMIT AND INSPECTIONS:
1. REPLACEMENT OF FLAT ROOF.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE

PERMIT AND INSPECTIONS:
1. INSTALLATION OF FENCE.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16071899

CASE ADDR: 4040 GALT OCEAN DR

OWNER: OCEAN MANOR CONDO ASSOC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILT A THIRD TIKI HUT WHEN ONLY 2 HAVE BEEN

PERMITTED.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. NEW ELECTRICAL CIRCUITS AND RECEPTACLES.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16050712 CASE ADDR: 2308 NW 6 CT

OWNER: SANTORSOLVA, VITO MICHELE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED HURRICANE SHUTTERS ON EXTERIOR WALL OPENINGS.

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLATION OF SPLIT A/C MECHANICAL SYSTEM.
NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. INSTALLATION OF CHAIN LINK FENCE.
NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16051422

CASE ADDR: 1249 SEABREEZE BLVD OWNER: MITTONE, HUGO F

MITTONE, PATRICIA N

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR REMODELING INCLUDING KITCHEN AND BATHROOMS.
- 2. TILED WALL COVERINGS IN BATHROOMS AND KITCHENS INCLUDING BUT NOT LIMITED TO WET AREAS.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF WATER SUPPLY AND WASTE LINES.
- 2. INSTALLATION OF BATHROOM AND KITCHEN FIXTURES NOT LIMITED TO SINKS, FAUCETS, VANITIES, TOILETS AND BIDETS.
- 3. INSTALLATION OF WATER HEATER.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF WIRING CIRCUITS.
- 2. INSTALLATION OF ELECTRICAL FIXTURES.
- 3. INSTALLATION OF BREAKER PANELS.
- 4. INSTALLATION OF NEW LIGHTING.
- 5. INSTALLATION OF NEW RECEPTACLES.

REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6)

GFI'S REQUIRED AS PER NEC 108.8

OUTLET SPACING AS REQUIRED UNDER NEC 210.52

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. REPLACEMENT OF MECHANICAL A/C SYSTEM.
- 2. INSTALLATION OF DUCT WORK AND REGISTERS.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. INSTALLATION AND REPLACEMENT OF DOORS AND WINDOWS.

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

._____

CASE NO: CE15101515
CASE ADDR: 1107 NW 11 ST
OWNER: RIVERO, FACUNDO

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR REMODELING.
- 2. DRYWALL HAS BEEN INSTALLED.
- 3. BEARING WALLS ARE BEING ALTERED.
- 4. NON-BEARING WALLS HAVE BEEN ALTERED.
- 5. PARTITIONS HAVE BEEN MOVED.
- 6. INTERIOR FLOOR PLAN CONFIGURATION HAS BEEN ALTERED.

FBC(2014) 105.3.1.4.3

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR DEMOLITION OF NON-BEARING WALLS.
- 2. INTERIOR DEMOLITION OF BEARING WALLS.
- 3. DRYWALL HAS BEEN REMOVED AND REPLACED.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM. THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE

FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. WATER SPIGOTS ON EXTERIOR OF DWELLING HAVE BEEN REPLACED.
- 2. NEW WASTE LINES AND CLEANOUTS HAVE BEEN INSTALLED.
- 3. NEW WATER SUPPLY LINES IN LAUNDRY ROOM, KITCHEN AND BATHROOMS.
- 4. PLUMBING FIXTURES ARE BEING REPLACED IN KITCHEN, BATHROOMS AND LAUNDRY ROOMS.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM. THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. CIRCUITS IN BREAKER PANEL ARE BEING MODIFIED.
- 2. NEW CIRCUITS ARE BEING INSTALLED IN KITCHENS, BATHROOM, LAUNDRY ROOM AND OTHER LIVING AREAS.
- 3. NEW FIXTURES ARE BEING INSTALLED IN KITCHENS, BATHROOM, LAUNDRY ROOM AND OTHER LIVING AREAS.
- 4. SWITCHES AND OUTLETS ARE BEING REPLACED AND MODIFIED.

FBC(2014) 105.3.1.5

WHERE APPLICABLE PERMIT REQUIREMENTS MUST HAVE SUPPORTING DOCUMENTATION FROM A QUALIFIED DESIGN PROFESSIONAL.

SUBMIT 2 SETS OF DRAWINGS/PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

MODIFICATIONS MADE PRIOR TO OBTAINING THE REQUIRED PERMITS MAY BE REQUIRED TO BE UNCOVERED FOR INSPECTIONS AND/OR CERTIFIED BY A LICENSED DESIGN PROFESSIONAL SOLELY AT THE DISCRETION OF THE BUILDING OFFICIAL. THIS INCLUDES BUT IT IS NOT LIMITED TO, ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 115.1

DUE TO THE ONGOING NATURE OF THE WORK WITHOUT PERMITS A STOP WORK ORDER HAS BEEN ISSUED AND ANY FURTHER WORK AND ALTERATIONS MAY BE SUBJECT TO THE MAXIMUM PENALTIES OF UP TO \$500 PER DAY PER VIOLATION UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

CASE NO: CE15102497

CASE ADDR: 1213 NW 14 ST

OWNER: MOONEY, CHRISTINA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.3.1.4.18

THE FENCE AND GATE NEEDS TO HAVE A PROFESSIONAL DESIGNER'S DRAWINGS WITH THE WINDS PRESSURE CALCULATIONS OR THE NOA IF APPLICABLE AS PER FBC(2014) 2224.1 FOR CHAIN LINK AND FBC(2014) 2328.1 FOR WOOD FENCE, IT MUST SHOW THE SCOPE OF THE WORK WITH THE INSTALLATION DETAILS AND IT MUST BE APPROVED BY ZONING TO BE INSTALLED ON THAT LOCATION.

1. A WOOD FENCE WAS ERECTED WITHOUT THE REQUIRED PERMITS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15111269
CASE ADDR: 1117 NW 4 AVE
OWNER: MAYNARD, JUNIOR
INSPECTOR: FRANK ARRIGONI
PRESENTED BY MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

DURING AN ONSITE INSPECTION OF THIS PROPERTY FOR A REQUEST TO VOID A EXPIRED FENCE PERMIT I NOTICED WORK HAD BEEN DONE:

- 1. WINDOW AND DOOR REPLACEMENT.
- 2. KITCHEN AND BATH PLUMBING FIXTURE REPLACEMENT.
- 3. ELECTRICAL SERVICE UPGRADE.
- 4. PLUMBING PIPE TIED INTO CLEAN OUT CAP.
- 5. IT APPEARS THE FLAT ROOF HAS BEEN REROOFED.
- 6. THERE IS A WOOD FENCE THAT WAS NOT PERMITED.

12/23/15 A REVIEW OF THE ORIGINAL PLAN AND THE ATF PLAN SUBMITTED SHOWS:

- 1. THE LAUNDRY WAS A CLOSET AND THE PORCH HAS BEEN CONVERTED TO A BEDROOM.
- 2. THE FRONT ENTRANCE HAS BEEN RELOCATED. THIS CAN BE SEEN IN PHOTOS ON BCPA WEB SITE.
- 3. THE A/C SYSTEM HAS BEEN ALTERED. DUCT WORK HAS BEEN ADDED TO THE BEDROOM ADDITION.
- 4. THE A/C AIR HANDLER AND CONDENSING UNITS REPLACED.

CASE NO: CE15100973

CASE ADDR: 3000 E SUNRISE BLVD # 16B

OWNER: COPPOLA, PAUL INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS CREATING AN OPENING BETWEEN TWO SEPARATE CONDO UNITS WHERE THE CONDO UNITS ARE NOW JOINED TOGETHER WITHOUT THE CORRECT PERMIT TYPE, A UNITY OF TITLE AND/OR REQUIRED

REVISIONS AND INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16081259

CASE ADDR: 209 N FTL BEACH BLVD 3E

OWNER: CERVIONE, JOHN A INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

 FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16090154

CASE ADDR: 1509 N FTL BEACH BLVD OWNER: NUCCI, MARY J H/E

NUCCI, DANIELLE W

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS OF A CARPORT AND ROOF STRUCTURE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

CASE NO: CE16090595 CASE ADDR: 3134 NE 9 ST

OWNER: CHIEFTAIN HOLDINGS LP

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS INTERIOR DEMOLITION AND INTERIOR REMODELING INVOLVING STRUCTURAL, ELECTRICAL, MECHANICAL AND PLUMBING PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16020922

CASE ADDR: 2181 NE 67 ST # 611 OWNER: RABAH, INNA BILOUS

RABAH, MAHIR

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES

BUT IS NOT LIMITED TO:

1. THE COMPLETE DEMOLITION OF THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE DEMOLITION OF THE KITCHEN AND BATHROOM PLUMBING WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE DEMOLITION OF THE KITCHEN AND BATHROOM ELECTRICAL WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE ALTERATION OF THE MECHANICAL VENTILATION FOR THE KITCHEN WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16031396

CASE ADDR: 2829 NE 30 ST # 205 OWNER: VAHER, ENNO & CARMEN

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS OF THE KITCHEN AND BATHROOM BEING REMODELED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16040122

CASE ADDR: 2175 NE 56 ST # 214 OWNER: YANOFSKY, STUART B

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES

BUT IS NOT LIMITED TO:

1. ALTERATIONS OF THE KITCHEN AND BATHROOM MADE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16070025

CASE ADDR: 401 RIVIERA ISLE 503 OWNER: BROOKS, CHRISTOPHER

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS, DEMOLITION AND REMODELING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE INCLUDING AN ELECTRICAL PANEL REPLACED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16071233

CASE ADDR: 1920 S OCEAN DR # 501

OWNER: BOURKE, DONALD INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING, DRYWALL AND CHIPPING HOLES THROUGH A SOLID CONCRETE BEAM AND EXPOSING REBAR WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE INCLUDING INSTALLING A TANKLESS WATER HEATER WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. EXTENSIVE ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT AT A MINIMUM WILL APPLY AND BASED ON THE CIRCUMSTANCES AND SEVERITY OF THE VIOLATIONS AND CITY RESOURCES INVOLVED THIS CASE MAY BE SUBJECT TO FOUR TIMES THE FEE UNDER SECTION 9-47. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERTY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16071264 CASE ADDR: 2758 NE 15 ST

OWNER: CAMBRIDGE APARTMENTS E & W LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. INTERIOR AND EXTERIOR REMODELING INVOLVING STRUCTURAL, ELECTRICAL, PLUMBING AND MECHANICAL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16071518 CASE ADDR: 5405 NE 22 TER KNEZEVIC, ANA OWNER: KNEZEVICH, DAVID

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS AND REMODELING PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16080256 CASE ADDR: 2128 NE 63 ST

OWNER: REALTY FIRE IMPERIAL POINT LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR DEMOLITION AND RENOVATIONS INCLUDING STRUCTURAL, ELECTRICAL, MECHANICAL AND PLUMBING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

CASE NO: CE16080490 CASE ADDR: 3761 SW 1 ST

OWNER: MARQUEZ, YAQUELINE INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 101.4.4.1.1

1. THE FRONT YARD HAS BEEN COMPLETELY PAVED OVER. RAIN WATER NOW FLOWING INTO THE STREET.

FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED IN THE FOLLOWING MANNER:

- 1. THE CARPORT HAS BEEN ENCLOSED CREATING ADDITIONAL LIVING SPACE.
- 2. AN ALUMINUM ROOF HAS BEEN INSTALLED ON THE WEST SIDE OF THIS PROPERTY.
- 3. THE FRONT YARD OF THIS PROPERTY HAS BEEN PAVED OVER.
- 4. A STORAGE SHED HAS BEEN INSTALLED AT THE REAR OF THE PROPERTY.

FBC(2014) 105.3.1.4.5

1. ELECTRICAL CIRCUITS HAVE BEEN ADDED TO THE ENCLOSURE.

FBC(2014) 105.3.1.4.15

1. WINDOW INSTALLED IN THE ENCLOSING WALL.

FBC(2014) 105.3.1.4.18

1. ALUMINUM FENCE INSTALLED AROUND THE FRONT OF THE PROPERTY WITH DRIVE GATES.

FBC(2014) 110.2

ACCESS TO PROPERTY BOTH INSIDE AND OUT REQUIRED TO DETERMINE IF ADDITIONAL VIOLATIONS EXIST.

FBC(2014) 110.6

REQUIRED INSPECTIONS FOR THE WORK COVERED IN THIS CASE MUST BE COMPLETED.

HEARING TO IMPOSE FINES

CHAPTER 11, FORT LAUDERDALE, CODE OF ORDINANCES

CASE NO: CE08070448 CASE ADDR: 1431 NW 11 PL

OWNER: DRAGOSLAVIC, GORAN

DRAGOSLAVIC, TERESA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2007) 105.1

THE PROPERTY SUSTAINED MAJOR DAMAGE TO THE

STRUCTURE AND THE INTERIOR CAUSED BY A FIRE BACK

ON JULY 7, 2008.

A STOP WORK ORDER WAS ISSUED ON JULY 11, 2011 FOR WORK IN PROGRESS. ALL THE REPAIRS WERE PERFORMED

WITHOUT OBTAINING THE REQUIRED PERMITS AND

INSPECTIONS:

1. THE ELECTRICAL SYSTEM WAS DAMAGED AND IT HAS BEEN REPAIRED.

2. THE FAMILY ROOM CEILING RAFTERS WITH THE ROOF DECK WERE COMPLETELY BURNED AWAY. THEY HAVE BEEN REPLACED.

3. COMPLETE INTERIOR RESTORATION: ALL THE ELECTRICAL AND PLUMBING FIXTURES, THE DRYWALL ON THE CEILING AND WALLS, WITH ALL THE CABINETRY WERE REPLACED.

4. THE AIR CONDITIONING SYSTEM HAS BEEN REPLACED IN WHOLE OR IN PART FROM THE FIRE DAMAGE.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

CASE NO: CE15041350 CASE ADDR: 1162 NW 9 TER

OWNER: MERSAN HOLDINGS LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. STRUCTURAL, PLUMBING AND ELECTRICAL ALTERATIONS ARE BEING DONE TO THE BUILDING. ALL THE WINDOWS AND DOORS WERE REPLACED IN THE OPENINGS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING AND INSPECTION PROCESS.

CASE NO: CE15102378

CASE ADDR: 680 TENNIS CLUB DR # 301

OWNER: LOPEZ, DENNIS R

LOPEZ, DENNIS A

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS.

- 1. WORK W/O PERMIT IN PROGRESS, THE INTERIOR OF THE UNIT WAS GUTTED WITHOUT A DEMOLITION PERMIT.
- 2. RENOVATION ARE BEING DONE AS FRAMING, ELECTRICAL, PLUMBING AND MECHANICAL WITHOUT THE PROPER PERMITS AND INSPECTIONS, INCLUDING THE OPENINGS ON THE FIRE PARTITONS.
- 3. WINDOWS WERE REPLACED.
- 4. CENTRAL A/C IS BEING REPLACED AND THE DUCT WORK IS BEING ALTERED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15102509

CASE ADDR: 2500 E COMMERCIAL BLVD

OWNER: ALTO PROPERTY MANAGEMENT LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS COMMERCIAL SPACE HAS BEEN COMPLETELY
REMODELED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. FRAMING AND DRYWALL INSTALLED WITHOUT THE
REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING FIXTURES INSTALLED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WIRING AND DEVICES INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THIS COMMERCIAL OFFICE SPACE AND THE ADJOINING UNITS, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED AND BROUGHT INTO COMPLIANCE PER FLORIDA BUILDING CODE.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE13080252

CASE ADDR: 2500 E COMMERCIAL BLVD

OWNER: ALTO PROPERTY MANAGEMENT LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR RENOVATIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2010) 105.4.4

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING FIXTURES INSTALLED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WIRING AND DEVICES INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE MECHANICAL SYSTEM IS BEING ALTERED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

CASE NO: CE15120488 CASE ADDR: 5501 NE 25 AVE OWNER: ATLANTIC LOFT LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS OF THE POOL DECK AREA WHERE A WALL AND WOOD FENCE WERE REMOVED AND AN ALUMINUM FENCE WAS INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. AN ALUMINUM FENCE INSTALLED WITHIN FIVE FEET OF THE POOLS WATER EDGE WHICH REQUIRES AN ELECTRICAL BONDING AND THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15061470
CASE ADDR: 1638 RIVER LN
OWNER: EVANS, JOHN
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE INTERIOR AND EXTERIOR REMODELLING BEING DONE WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE REMODELLING BEING DONE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE REMODELLING WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE INTERIOR AND EXTERIOR REMODELLING BEING DONE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15011493

CASE ADDR: 401 SW 4 AVE # 605

OWNER: TOTH, ILDIKO INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2010) 105.1

- 1. THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE DEMOLITION OF THE KITCHEN AND TWO BATHROOMS WITHOUT THE REQUIRED PERMITS.
- 2. THIS CONDO UNIT HAS ALSO BEEN ALTERED WITH THE COMPLETE REMODELING OF THE ENTIRE UNIT WHICH INCLUDES BUT IS NOT LIMITED TO STRUCTURAL WORK BEING DONE WHICH INCLUDES BUT IS NOT LIMITED TO FRAMING, DRYWALL AND TILE BACKING BOARD WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE REMODELING OF THE KITCHEN AND BATHROOMS INCLUDING BUT NOT LIMITED TO THE ALTERATION OF THE MECHANICAL DUCT WORK AND FANS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE REMODELING OF THE UNIT WHICH INCLUDES BUT IS NOT LIMITED TO THE REMOVAL AND REPLACEMENT OF THE PLUMBING FIXTURES WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE RENOVATION OF THE ENTIRE UNIT WHICH INCLUDES BUT IS NOT LIMITED TO ELECTRICAL WIRING BEING INSTALLED AND ALTERING THE EXISTING ELECTRICAL DEVICES AND SWITCHES WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THIS CODE CASE WILL FIRST REQUIRE THAT THE CONDO UNIT OWNER HIRE A LICENSED ARCHITECT OR ENGINEER TO PROVIDE A COMPLETE SET OF DRAWINGS TO ADDRESS ALL THE VIOLATIONS AND THE NEEDED CORRECTIONS. BECAUSE OF THE SEVERITY OF THE ELECTRICAL WORK THAT WAS DONE THIS WILL BE A REQUIREMENT IN ORDER TO OBTAIN PERMITS. THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL THE REQUIRED PERMITS, SCHEDULE AND PASS ALL THE REQUIRED INSPECTIONS, PROPERLY CLOSE OUT ALL THE REQUIRED PERMITS TO FULLY COMPLY AND CLOSE THIS CODE CASE.

CASE NO: CE16011103

CASE ADDR: 2624 NE 30 PL # 103B OWNER: WILLIAMS, ASHLEY DAWN

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. RENOVATIONS AND WORK BEING DONE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS CONDO BUILDING/UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. HAVING MECHANICAL ALTERATIONS MADE WHERE A/C UNITS HAVE BEEN INSTALLED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL INSTALLED AND/OR ALTERED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15100439 CASE ADDR: 2000 NE 17 WY

OWNER: SCHRONEN, GARY & PEGGY H/E

HOWELL, J & C

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. A TIKI HUT BEING BUILT IN THE REAR OF THE PROPERTY WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

._____

CASE NO: CE16040644

CASE ADDR: 325 ISLE OF CAPRI

OWNER: GALLUZZO, GEORGE R JR & MELISSA

INSPECTOR: FRANK ARRIGONI
PRESENTED BY MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THE PROPERTY HAS BEEN ALTERED IN THE FOLLOWING

MANNER.

1. THE DOCK HAS BEEN REPLACED ON THE EXISTING PILING AND STAIRS ADDED TO THE SOUTH END.

FBC(2014) 105.3.1.4.4

1. WATER LINES INSTALLED ON DOCK

FBC(2014) 105.3.1.4.5

1. ELECTRICAL SERVICE ADDED TO DOCK

FBC(2014) 110.6

THE REQUIRED INSPECTIONS FOR THIS WORK WERE NOT DONE.

CASE NO: CE15080754

CASE ADDR: 1706 NW 14 CT

OWNER: TUCHOW, TYLER

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. GARAGE WAS CONVERTED INTO LIVING SPACE.

2. CONSTRUCTION OF A SECOND BATHROOM.

3. AIR CONDITIONING SYSTEM CHANGE OUT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

CASE NO: CE14090494

CASE ADDR: 1205 NE 3 AV

OWNER: BLAKE, HEATHER

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO: 1. BATHROOM REMODEL.

CASE NO: CE14100834 CASE ADDR: 3601 SW 2 ST

OWNER: GRAHAM, VINCENT M & JACQUELINE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. ADDITION 784 SF 1STY

FAMILYROOM/BATHROOM/PLAYROOM.

2. ROOF FOR ADDITION.

FBC(2010) 105.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCTWORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS

CONNECTED TO THE MECHANICAL SYSTEM.

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. MECHANICAL FOR ADDITION.

FBC (2010) 105.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. PLUMBING FOR ADDITION.

FBC(2010) 105.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM. THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. ELECTRIC FOR ADDITION.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15080382 CASE ADDR: 2151 NW 29 TER

OWNER: KINGS, TERRY JR EST

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.3

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. AFTER FIRE, INTERIOR OF DWELLING HAS BEEN DEMOLISHED. WALL AND CEILING COVERINGS REMOVED.
- 2. ELECTRICAL AND PLUMBING FIXTURES HAVE BEEN ALTERED AND/OR REMOVED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16010691 CASE ADDR: 1133 NW 7 AV

OWNER: TIITF/HRS-YOUTH SERV

BROWARD CHILDRENS SHELTER

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CHANGED THE FLOORPLAN CONFIGURATION OF THE APPROVED USE AS A DUPLEX INTO A HALFWAY HOUSE WITH MULTIPLE SLEEPING ROOMS.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. CHANGED THE CONFIGURATION OF THE MECHANICAL SYSTEM FROM THAT OF A DUPLEX TO A HALFWAY HOUSE WITH MULTIPLE SLEEPING QUARTERS.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CHANGED THE CONFIGURATION OF THE PLUMBING

SYSTEM FROM THAT OF A DUPLEX TO A HALFWAY HOUSE WITH MULTIPLE SLEEPING QUARTERS.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CHANGED THE CONFIGURATION OF THE ELECTRICAL SYSTEM FROM THAT OF A DUPLEX TO A HALFWAY HOUSE WITH MULTIPLE SLEEPING QUARTERS.

FBC(2014) 105.3.1.5

SUBMIT "AS BUILT" ARCHITECTURAL DRAWINGS AND THE SCOPE OF WORK COVERING ALL EXISTING STRUCTURES AND MODIFICATIONS.

ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF DUPLEX TO HALFWAY HOUSE WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT. COMMON ROOF HAS ENJOINED THE BUILDING ON THIS PARCEL WITH BUILDING ON ADJACENT PARCEL.

CASE NO: CE15091002 CASE ADDR: 1135 NW 7 AV

OWNER: TIITF/HRS-YOUTH SERV

BROWARD CHILDRENS SHELTER

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. PAVED AND STRIPPED PARKING AREA WITHOUT ACQUIRING THE REQUIRED PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16010689 CASE ADDR: 1135 NW 7 AV

OWNER: TIITF/HRS-YOUTH SERV

BROWARD CHILDRENS SHELTER

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILT BREEZEWAY TO JOIN ADJACENT BUILDINGS ON PROPERTIES IDENTIFIED WITH DIFFERENT FOLIO NUMBERS. IN ADDTION THE INTERIOR FLOOR PLAN CONFIGURATION HAS BEEN CHANGED TO OFFICES, STORAGE AND A KITCHEN.

FBC(2014) 105.3.1.4.10

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CONSTRUCTED ROOF BREEZEWAY WITH BUILDINGS ON ADJACENT PARCELS.

FBC(2014) 105.3.1.5

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS: SUBMIT "AS BUILT" ARCHITECTURAL DRAWINGS AND THE SCOPE OF WORK COVERING ALL EXISTING STRUCTURES AND MODIFICATIONSBUT NOT LIMITED TO:

1. ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2010) 111.1.1

THIS BUILDING WAS JOINED WITH A COMMON ROOF BREEZEWAY WITH 2 ADJACENT BUILDINGS WITH DIFFERENT PROPERTY FOLIO NUMBERS. THE APPROVED USE OF THIS BUILDING IS FOR HALFWAY HOUSE PER PERMIT 90006599 AND THE USE IS THAT OF AN ADMINISTRATIVE BUILDING WITH OFFICES, STORAGE AND KITCHEN.

CASE NO: CE15071515 CASE ADDR: 1135 NW 7 AV

OWNER: TIITF/HRS-YOUTH SERV

BROWARD CHILDRENS SHELTER

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. ALL WORK AND CORRECTIONS REQUIRING PERMITTING MUST COMPLY WITH THIS SECTION OF THE CODED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

FBC(2014) 1003.6

WINDOWS AND DOORS HAVE BEEN BLOCKED LIMITING EGRESS AS REQUIRED BY CODE.

FBC(2014) 1006.1

EMERGENCY EXIT LIGHTS MUST BE MADE FUNCTIONAL AS REQUIRED BY CODE.

FBC(2014) 1006.3

EMERGENCY EXIT LIGHTS MUST BE MADE FUNCTIONAL AS REQUIRED BY CODE.

FBC(2014) 1008.1.9.1

ALL DOORS MUST HAVE LATCHES AND HANDLES AS TO BE ABLE TO BE OPENED FROM THE INTERIOR OF THE FLOOR AREA THEY SERVICE AS REQUIRED BY CODE.

FBC(2014) 1008.1.9.3 4.

DOUBLE KEYED DEAD BOLTS MUST BE REMOVED AS THEY PREVENT EGRESS FROM THE FLOOR AREA THEY SERVE AS REQUIRED BY CODE.

FBC(2014) 1029.1

ALL ROOMS THAT ARE DESIGNED WITH WINDOWS THAT CAN SERVE AS A MEANS OF EGRESS MUST HAVE AT MINIMUM ONE WINDOW UNBLOCKED AS TO SERVE AS THE SECONDARY MEANS OF EGRESS AS REQUIRED BY CODE.

FBC(2014) 1522.3.4

NO WIRE SHALL BE WITHIN THE PHYSICAL LIMITS IDENTIFIED BY THE SECTION OF THIS CODE.

NEC 110.26

WORKING SPACE AROUND PANELS MUST MEET THIS SECTION OF THE CODE.

NEC(2005) 110.12

ALL UNSUSED OPENING IN ELECTRICAL PANELS MUST BE SEALED.

NEC(2005) 110.22

ALL PANELS AND MEANS OF DISCONNECT MUST BE IDENTIFIED AND LABELED IDENTIFYING THE CIRCUITS THEY SERVE.

NEC(2005) 110.27

ALL ENERGIZED CONNECTIONS MUST BE GUARDED FROM UNAUTHORIZED CONTACT.

NEC(2005) 210.8

AREAS REQUIRING GFI PROTECTION ON THE EXTERIOR AND WET KITCHEN AND BATHROOM AREA MUST BE MADE OPERABLE.

NEC(2005) 230.24

PANEL CANNOT BE BLOCKED AND MUST BE MADE ACCESSIBLE FOR EMERGENCY DISCONNECT IF REQUIRED.

NEC(2005) 406.11

DWELLING UNITS MUST HAVE TAMPER-RESISTANT RECEPTACLES.

NEC(2005) 408.38

ALL PANELS DISCONNECT BOXES MUST BE SECURED AS TO NOT HAVE ACCESS TO ENERGIZED CONNECTIONS OR HAVE A DEAD FRONT COVER.

NEC (2005) 408.4

ALL PANELS AND MEANS OF DISCONNECT MUST BE IDENTIFIED AND LABELED IDENTIFYING THE CIRCUITS THEY SERVE.

NEC(2005) 440.22(A)

CIRCUIT/FUSE/BREAKER MUST BE COMPATIBLE AND BE ABLE TO CARRY THE LOAD OF THE MECHANICAL EQUIPMENT THEY SERVE.

NEC (2005) 440.22 (C)

CIRCUITS MUST MEET MANUFACTURERS CRITERIA.

CASE NO: CE16010692 CASE ADDR: 1141 NW 7 AV

OWNER: TIITF/HRS-YOUTH SERV

BROWARD CHILDRENS SHELTER

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CHANGED THE FLOORPLAN CONFIGURATION OF THE APPROVED USE AS A DUPLEX INTO A HALFWAY HOUSE WITH MULTIPLE SLEEPING ROOMS.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. CHANGED THE CONFIGURATION OF THE MECHANICAL SYSTEM FROM THAT OF A DUPLEX TO A HALFWAY HOUSE WITH MULTIPLE SLEEPING QUARTERS.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CHANGED THE CONFIGURATION OF THE PLUMBING SYSTEM FROM THAT OF A DUPLEX TO A HALFWAY HOUSE WITH MULTIPLE SLEEPING QUARTERS.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CHANGED THE CONFIGURATION OF THE ELECTRICAL SYSTEM FROM THAT OF A DUPLEX TO A HALFWAY HOUSE WITH MULTIPLE SLEEPING QUARTERS.

FBC(2014) 105.3.1.5

SUBMIT "AS BUILT" ARCHITECTURAL DRAWINGS AND THE SCOPE OF WORK COVERING ALL EXISTING STRUCTURES AND MODIFICATIONS.

1. ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF DUPLEX TO HALFWAY HOUSE WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT. COMMON ROOF HAS ENJOINED THE BUILDING ON THIS PARCEL WITH BUILDING ON ADJACENT PARCEL.

CASE NO: CE15092059
CASE ADDR: 1544 NW 9 AVE
OWNER: KDE OF FL 1 LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REMODELING AND ALTERATIONS TO THE STRUCTURE. WINDOWS, DOORS, WALLS, BATHROOMS REMODEL, KITCHEN REMODEL, PLUMBING.

FBC(2014) 105.19.2

THE BUILDING OFFICIAL AT HIS/HER DISCRETION SHALL INTERPRET THE BUILDING CODE AND COMPLIANCE REQUIREMENTS.

FBC (2014) 105.3.1.4.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. STRUCTURAL MODIFICATIONS OF INTERIOR WALLS.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION OF DOORS AND WINDOWS.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND IT'S COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT LIMITED TO:

1. BATHROOM REMODEL WITH PLUMBING ALTERATIONS.

FBC(2014) 105.3.1.5

WHERE APPLICABLE PERMIT REQUIREMENTS MUST HAVE SUPPORTING DOCUMENTATION FROM A QUALIFIED DESIGN PROFESSIONAL.

FBC(2014) 105.4.1.2 OWNER RESPONSIBILITY.

FBC(2014) 109.3.3

THIS CODE CASE WILL REQUIRE ALL PERMITS TO BE DOUBLE FEE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A SINGLE FAMILY HOME TO A DUPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

FBC(2014) 115.1

STOP WORK ORDER ISSUED SINCE WORK IS ONGOING WITHOUT THE REQUIRED PERMITS.

FBC(2014) 116.1.2

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE AND IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED:

1. PER FLORIDA BUILDING CODE WORK WITHOUT PERMIT IS DEEMED TO BE UNSAFE.

CASE NO: CE15101733

CASE ADDR: 1216 CHATEAU PARK DR

OWNER: S R SINGH ENTERPRISES LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ALTERATIONS BY ENCLOSING THE GARAGE OF THE STRUCTURE.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REPLACEMENT OF EXTERIOR DOORS AND WINDOWS WILL REQUIRE PERMITTING.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. PLUMBING FIXTURES INCLUDING WATER HEATER.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM. THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ELECTRICAL FIXTURES, SWITCHES AND OULETS.
- 2. CIRCUITRY FOR WATER HEATER.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16020021

CASE ADDR: 6303 NW 9 AVE # 9

OWNER: 6303 L L C INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS TENANT SPACE HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF WALK-IN FOOD TAKE-OUT TO SIT DOWN RESATURANT WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

FBC(2014) 105.3.1.4.11

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. COMMERCIAL KITCHEN EXHAUST HOOD WITH FIRE SUPRESSION SYSTEM.
- 2. TWO WALK-IN COMMERCIAL COOLERS.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. WATER HEATER.
- 2. DINING ROOM SINK WITH FIXTURES.
- 3. ONE SMALL STAINLESS STEEL SINK AND ONE DOUBLE STAINLESS STEEL SINK WITH FIXTURES.
- 4. VANITY SINK WITH TOILET.

FBC(2014) 105.3.1.5

SUBMIT 2 SETS OF DRAWINGS/PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16021843 CASE ADDR: 1420 NE 15 AV

OWNER: BORRAS, ALEXANDRA L

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILDING A WOOD FRAME CARPORT ONTO EXISTING DRIVEWAY.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16030350 CASE ADDR: 1535 NW 10 AV

OWNER: WASHINGTON, JEANETTE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.18

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. MODIFIED EXISTING FENCE FROM ORIGINAL APPROVED CONFIGURATION.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED NEW PLUMBING AT BACK OF PROPERTY.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW ELECTRICAL 220V OUTLET.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16032371
CASE ADDR: 2327 SW 17 AVE
OWNER: JANDEBEUR, PATRICK

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:
1. BUILT SCREEN ENCLOSURE STRUCTURE AT BACK ELEVATION OF BUILDING.

2. CONSTRUCTION OF SCREEN ENCLOSURE STRUCTURE IN PROGRESS AT RIGHT ELEVATION OF BUILDING.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16050163 CASE ADDR: 1533 NW 19 AVE

OWNER: DRAGOSLAVIC, SLAVOLJUB & MARA

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILT CARPORT.

- 2. BUILT FRONT PORCH.
- 3. BUILT ADDITION.
- 4. INSTALLED INTERIOR DROP CEILING.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. ILLEGALLY INSTALLED PLUMBING FIXTURES AND ALTERED THE PLUMBING SYSTEM SO THAT SEWAGE IS BACKING UP AT THE CLEANOUT BY THE SIDEWALK.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. INSTALLED ELECTRICAL FIXTURES AND WIRING ABOVE THE DROP CEILING.

FBC(2014) 105.3.1.4.10

THE FOLLOWING DESCRIBED WORK REQUIRES A ROOF PERMIT AND INSPECTIONS:

1. ILLEGALLY INSTALLED ARCHITECTURAL SHINGLE ROOF.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. ILLEGALLY INSTALLED A SPLIT AIR CONDITIONING SYSTEM.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2014) 116.2.1.3.1

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE AND IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED:

1. DUE TO A FIRE THE STRUCTURE IS NOW DEEMED UNSAFE BY THE CITY.

CASE NO: CE16050504
CASE ADDR: 1537 NW 19 AV
OWNER: LUMAX USA LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILT ROOF CANOPY ON RIGHT ELEVATION OF DWELLING. CANOPY IS STRUCTURALLY ATTACHED TO 1X6 FASCIA BOARD.

FBC(2014) 105.3.1.4.10

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

 INSTALLED SPLIT MECHANICAL AIR CONDITIONING SYSTEM.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE16050534 CASE ADDR: 2900 NE 30 ST

OWNER: LAUDERDALE TOWER CONDO ASSN INC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE REQUIRED WORK TO BE DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE

FBC(2014) 110.6

VIOLATIONS ARE TO BE CORRECTED.

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F./CODE CASE PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 116.2.1.2.2

THE BUILDING HAS AREAS WHERE THERE IS CONCRETE DETERIORATION WHICH INCLUDES BUT IS NOT LIMITED TO BALCONY RAILINGS FAILING WHICH HAS CREATED AN UNSAFE CONDITION FOR THE BUILDING AND POSES POTENTIAL LIFE SAFETY ISSUES FOR THE OCCUPANTS OF THIS BUILDING.

CASE NO: CE16050574

CASE ADDR: 2500 NE 48 LA # 509 OWNER: KEBE, STANLEY W

GOLDFIELD, SUZANNE

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES

BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING, DRYWALL, REMODELING THE KITCHEN AND TWO BATHROOMS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16071180

CASE ADDR: 512 NW 15 TER

OWNER: PASCAL 2014 LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. THE INTERIOR FLOOR PLAN CONFIGURATION OF THIS SINGLE FAMILY HOME HAS BEEN ALTERED.
- 2. KITCHEN HAS BEEN REMODELED.
- 3. BATHROOM HAS BEEN REMODELED.
- 4. BATHROOM HAS BEEN ADDED.
- 5. FRONT PORCH HAS BEEN BUILT AND ENCLOSED.
- 6. SECOND ACCESSORY STRUCTURE HAS BEEN BUILT AT BACK OF PARCEL AND CONVERTED TO A SECOND OCCUPIED RESIDENCE.
- 7. UTILITY LAUNDRY CLOSET BUILT AT BACK OF PRIMARY STRUCTURE.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF PLUMBING FIXTURES IN KITCHENS AND BATHS.
- 2. INSTALLATION OF WATER SUPPLY AND WASTE LINES TO SERVICE BATHROOM ADDED, BATHROOM REMODEL LAUNDRY AND WATER HEATER.
- 3. INSTALLATION OF WATER HEATER.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF WIRING CIRCUITS TO SERVICE WATER HEATER, WASHER-DRYER, MECHANICAL SYSTEM, RECEPTACLES AND FIXTURES.
- 2. INSTALLATION OF RECEPTACLES.
- 3. INSTALLATION OF BREAKER PANEL.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6)
GFI'S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF SPLIT MECHANICAL A/C SYSTEM.
- 2. INSTALLATION OF DUCT WORK.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF SINGLE FAMILY TO DUPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.
